



# **SUBJECT:** Large Canopy Collapse due to Snow and Ice

## **RECIPIENTS:** All Council Services (including schools)

### ISSUE DATE: 6<sup>th</sup> Dec 2010 REF: HSA1

## Large Canopy Collapse due to Snow and Ice build up





#### COMPACTED SNOW IS THREE TIMES HEAVIER THAN FRESHLY FALLEN SNOW

Due to the heavy snow fall and freezing temperatures over the last week some long/wide canopies may have a thick build up of compacted snow on them, in some causes at least 12" of build up, which may be placing some canopies under excessive strain/stress and/or weakening fixing points.

It is therefore essential that you assess any such canopies on your site to confirm the structural safety before allowing activities/access to take place within/under them.

This conformation assessment can be done through either:

- Mouchel Property Services Tel:01522 836222
- Your own property services contact/company/competent person
- The company who built/installed the canopy.

All assessments, findings and actions relating to this **MUST** be recorded

Clearing the snow should be part of a planned maintenance programme with due consideration given to a safe method of work.

**If you require further assistance or clarification on the subject please contact:** Mouchel Safety Adviser 01522 836714 or Corporate Health & Safety Ext:3675.

